- 1. Batterygoes in front floorboard.
- 2. Gas can in rearfloorboard
- 3. No. 9 wire 2 strands in 4 places on the hood -sheet metal to sheet metal only 4 on the trunk sheet metal to sheet metal only you may go around frame.
- 4. You may weld all 4 doors.
- 5. 3/4 all thread may be used for body mounts and you may have 2-3/4 all threads in trunk
- 6. May build a front bumper only 4x4 square tubing no bigger than quarter inch, otherwise must be original bumper
- 7. Bumpers may be welded directly to the frame-if so no bumper mounts are allowed-if not you may have a 4x4 mounting bracket 12" long for bumper. Mounts may be welded solid to frame on the outside!(NEED TO HAVE A SAFETY CHAIN WELDED OR BOLTED TO BUMPER THAT CONNECTS TO THE FRAME ON BOTH SIDES FOR SAFETY TO KEEP BUMPER FROM FLYING OFF)
- 8. You may weld rearends. Needs to be the factory rearend the car came with.
- 9. You may have an after-marketshifter and foot feet.
- 10. You may swap engines ...all engines must be stock.
- 11. Header and Stock Manifolds
- 12. Cage must be bolted to sheet metal. 1 brace on each door, 1 right behind front seat and dashbar.
- 13. Front window bars are allowed.
- 14. No slider shafts.
- 15. You may replace steering column.
- 16. Gas tank protector no further back than 40" from bottom of front seat must stay in front of rear axle.
- 17. NO Imperials or suicide door Lincolns
- 18. You may have 4 patch plates. 2 on each side 6 inches long. 6" x 6"

No Exceptions on these Rules...
If it is in the rules DO IT – If not DON'T

Check All Rules before Coming General Rules apply to all classes Contact Stacey Holsapple @217-923-1507 or Dustin McCullough @ 217-251-4614